33 CRYSTAL LANE AND CUL-DE-SAC

9-27-22 15 HAMLAND RD. IN BACKGROUND

HAY BALES FAILED TO KEEP SEDIMENTS OUT OF CB

9-27-22 REAR OF 15 HAVILAND RD. @ CRYSTAL LANE

CUL-DE-SAC

DIRT "RAMP" AND STOCKPILE @ 34 CRYSTAL LANE

9-27-22 MUD & HAYBALES AT C.B. IN FRONT OF 29 CRYSTAL LANE

9-27-22 MUD & TRACKING ON SOUTH SIDE OF CRYSTAL LA.

CRYSTAL LANE OUTFALL 24" FES IS UNDER FALLEN TREES

9-29-22 CHANNEL DOWN STREAM OF OUTFALL W/ THICK LAYER OF NEW SEDIMENTS

9-29-22 POND EAST OF CRYSTAL LANE